



J1-14	TO CASS	J3-3
J1-1	GND	J3-1
J1-13	FROM CASS	J3-7
J1-2	GND	J3-5
J1-12	CASS ON/OFF	J3-11
J1-3	GND	J3-9

J1- 14 PIN DIP FROM I/O BOARD
 J2- 50 PIN FROM PROCESSOR PARALLEL PORT
 J3- 64 PIN FROM BARRIER STRIP ASSY
 J4- 2 PIN PB RESET

J3-	TB2-	FUNCTION
34	17	SITE 5 SCU CONTROL
36	18	SITE 5 SCU CONTROL
38	19	SITE 5 SCU METER
40	20	SITE 5 SCU METER
42	21	SITE 5 TCU CONTROL
44	22	SITE 5 TCU CONTROL
46	23	SITE 5 TCU METER
48	24	SITE 5 TCU METER
50	25	SITE 6 SCU CONTROL
52	26	SITE 6 SCU CONTROL
54	27	SITE 6 SCU METER
56	28	SITE 6 SCU METER
58	29	SITE 6 TCU CONTROL
60	30	SITE 6 TCU CONTROL
62	31	SITE 6 TCU METER
64	32	SITE 6 TCU METER

Note -
 J3 CONNECTS TO REAR PANEL BARRIER STRIP/RFI FILTER ASSY (TB1 & TB2)
 PINOUTS & FUNCTIONS LISTED BELOW -

J3-	TB1-	FUNCTION
1	1	GROUND
3	2	TO CASS
5	3	GROUND
7	4	FROM CASS
9	5	GROUND
11	6	CASS ON/OFF
13	7	GROUND
15	8	ALARM
17	9	SITE 5 SCU CONTROL
19	10	SITE 5 SCU CONTROL
21	11	SITE 5 SCU METER
23	12	SITE 5 SCU METER
25	13	SITE 5 TCU CONTROL
27	14	SITE 5 TCU CONTROL
29	15	SITE 5 TCU METER
31	16	SITE 5 TCU METER

J3-	TB1-	FUNCTION
33	17	SITE 1 SCU CONTROL
35	18	SITE 1 SCU CONTROL
37	19	SITE 1 SCU METER
39	20	SITE 1 SCU METER
41	21	SITE 1 TCU CONTROL
43	22	SITE 1 TCU CONTROL
45	23	SITE 1 TCU METER
47	24	SITE 1 TCU METER
49	25	SITE 2 SCU CONTROL
51	26	SITE 2 SCU CONTROL
53	27	SITE 2 SCU METER
55	28	SITE 2 SCU METER
57	29	SITE 2 TCU CONTROL
59	30	SITE 2 TCU CONTROL
61	31	SITE 2 TCU METER
63	32	SITE 2 TCU METER

J3-	TB2-	FUNCTION
2	1	SITE 3 SCU CONTROL
4	2	SITE 3 SCU CONTROL
6	3	SITE 3 SCU METER
8	4	SITE 3 SCU METER
10	5	SITE 3 TCU CONTROL
12	6	SITE 3 TCU CONTROL
14	7	SITE 3 TCU METER
16	8	SITE 3 TCU METER
18	9	SITE 4 SCU CONTROL
20	10	SITE 4 SCU CONTROL
22	11	SITE 4 SCU METER
24	12	SITE 4 SCU METER
26	13	SITE 4 TCU CONTROL
28	14	SITE 4 TCU CONTROL
30	15	SITE 4 TCU METER
32	16	SITE 4 TCU METER

20 AUG 1980

SCHEMATIC - PCC SITE SELECT BOARD

P/N 0010-1411

C-115